Date: 15th September,2026

PRODUCT SAFETY RECALL, Issued by JP Cotton Mills

NAMAH Lynx 8.4 mm Dynamic Climbing Rope

Also supplied as Genius 8.4 mm Dynamic Rope

Stop using this rope immediately

If you have a NAMAH Lynx 8.4 mm or Genius 8.4 mm dynamic climbing rope, stop using it now. Do not use it for climbing, belaying, abseiling, rescue, work at height, or any other purpose where it could be called on to hold a fall.

The hazard

Testing has shown that this rope can break after arresting only a small number of falls, and below the number required by the standard EN 892 for dynamic mountaineering ropes. We have confirmed a non-compliance against the standard in our own testing.

A rope that breaks during a fall can cause serious injury or casualty.

The cause is under investigation. Until that investigation is complete, this rope must not be relied on to hold a fall.

How to identify the rope

Check the Batch number as: NL-8.4-5413-260511-01 , NL-8.4-5413-260530-01 , NL-8.4-5413-260603-01 , NL-8.4-5413-260629-01 , NL-8.4-5413-260705-01, marked on the end band at each end of the rope. Supplied between May 2026 and July 2026. Lengths supplied: 5 units, Total Meters- 380 meters

What you should do

1. Stop using the rope immediately.
2. Take it out of service so that nobody else can pick it up and use it. Do not lend it, sell it, give it away or donate it.
3. Contact us at info@namahropes.com to arrange a return.
4. Tell anyone who may have used or borrowed this rope, including climbing partners, clubs, gyms, schools, guiding operations and employers, that it must not be used.

What you will receive

You may choose either a full refund of the price you paid, or a replacement rope of equivalent or higher specification. You do not need proof of purchase.

Contact

M. Sharma, Sales Manager, JP Cotton Mills. m.sharma@namahropes.com.

If you are unsure whether your rope is affected, contact us and we will help you identify it. **Please pass this notice to anyone who may own or use this rope.**